Please complete every section daily and give to at ENV Station 001.

Date: <u>3.19.17</u> Time: <u>10.22</u> Initials: <u>DDD</u>

Outfall 009/010	Answers	
Substance discharged?	Y / (N)	
-If Yes, Color?	N	
-If Yes, Size / Area?	N	
Vac truck amount recovered	N	
Estimated oil recovered	N	
Length of sorbent boom replaced	L.	
Canal Appearance (winds, sheen, etc.)	NW-5 PC	


Date: 3-/9-/7
Time: 998
Initials: 008

Outfall 001	Answers	
Substance discharged?	Y / (N)	
-If Yes, Color?		
-If Yes, Size / Area?	N	
Vac truck amount recovered	N	
Estimated oil recovered	·	
Length of sorbent boom replaced	·	
Canal Appearance (winds, sheen, etc.)	MV-5 PC	

08-18-16;10:25PM;

Pit covers mustyremain on at all times

Date: 3/18/



Sump Pits	Clean	Oil Sheen & Color	Comments	
70k Room	\mathcal{X}			
6 Turbo Blower		Sump Water Diverted to Ash Pit		
7 Generator		Sump Water Diverted to Ash Pit		
5 Turbo Blower		Sump Water Diverted to Ash Pit		
7 Turbo Blower	h			
2300VAC Room	X			
8 Generator		Sump Water Diverted to Ash Pit		

If oil is found in sump pit contact KM to have the pit cleaned out.